



MARTEK® MARK 25

ULTRAPURE WATER DISSOLVED OXYGEN ANALYZER

MARTEK INSTRUMENTS INC. MANUFACTURERS OF WATER QUALITY INSTRUMENTATION



... for accurate, continuous, in situ monitoring of up to four ultrapure water dissolved oxygen measurements

Instruction Manual

Rev C 5/10

WARRANTY POLICY

Unless otherwise stated, MARTEK INSTRUMENTS, INC. warrants this equipment to be free from defects in material and workmanship and to perform in accordance with applicable specifications for five years (one year for portable equipment) from date of shipment. All conductivity sensors are guaranteed for life.

MARTEK will provide free service at the factory, including parts, labor and transportation back to the customer, for any malfunction of its products which are returned transportation charges prepaid.

Customers desiring to return a product to MARTEK for repair should contact the Service Department by telephone at (800) 628-8834 or fax (919) 790-2375 or via our website at www.martekinstruments.com to obtain return authorization. The information required at this time will be the complete model number and serial number of the product and a brief description of the problem.

All shipments to MARTEK must be freight prepaid and addressed as follows:

**MARTEK INSTRUMENTS, INC.
5201 Old Poole Rd
Raleigh, NC 27610
Attn: Repair Department**

A complete and detailed statement of the reason for return must accompany the unit. If possible, include a copy of sample reading or a printout.

Returned units must be packed as well as they were when first shipped. If possible, use the original packing. Do not return detachable cords or manuals with the unit.

MARTEK reserves the right to void this warranty if the product has been subjected to misuse, neglect, accident, improper installation or application, and for consumable items such as batteries, membranes, or solutions.

This warranty is expressly in lieu of all other obligations or liabilities on the part of MARTEK. MARTEK neither assumes nor authorizes any other person or organization to assume on behalf of Martek any other liability in connection with the sales or use of MARTEK instrumentation.

Mark 25 Dissolved Oxygen Table of Contents

Chapter		Page
1.	General Description	4
2.	Specifications	5
A	Front Dimensions	6
B	Rear Dimensions	6
C	Right Side Dimensions	7
D	Left Side Dimensions	7
3.	Installation	8
A	Unpacking	8
B	Panel Cutout for Monitor	9
C	Mounting Analyzer	9
D	Sensor Dimensions	10
E	Flow Chamber Dimensions	11
F	Input and Output connections	12
4.	Operation	13
A	Keyboard and display	13
B	CALIB key	16
C	Calibrating Temperature	18
D	Calibrating Dissolved Oxygen	21
E	Setting Alarms	24
F	Setting Recorder Outputs	28
G	Setting the Temperature Device	32
H	Setting the Password	34
I	Setting the ID Number	35
J	Changing the Serial Output	37
K	Setting the Auto-Ranging Function	39
5.	Maintenance	40
A	Troubleshooting	40
6.	Parts List	41
	Appendix A	42

1. General Description

The Mark 25 Dissolved Oxygen Analyzer is a simple, low cost, **4 channel**, microprocessor-based monitoring system designed for ultrapure water applications. The system consists of a readout module that can be used with up to four galvanic-style dissolved oxygen sensors; each sensor being placed into a separate flow chamber.

A large 4 digit LED display indicates either **temperature**, **parts-per-million (ppm)** or **parts-per-billion (ppb) dissolved oxygen**. An 8-key membrane keypad allows the operator to quickly setup and calibrate the analyzer.


The Mark 25 measures dissolved oxygen in **four ranges**; 0-20 ppb, 0-200 ppb, 0-2 ppm, and 0-20 ppm. Automatic calibration within the Mark 25 provides a fairly reliable measurement. However, comparison to a referee system remains the most accurate method of calibration available. (Please refer to Martek's **Mark 21 Portable Dissolved Oxygen Analyzer** for further information).

Four alarm set points with relay contacts are standard in addition to four isolated analog recorder outputs (0-20 mA) *and* a serial RS232 digital output for hookup to external recording equipment. For maximum flexibility, **alarm set points and analog outputs can be assigned to any range on any parameter on any channel.**

Housed in a ¼ DIN corrosion-resistant plastic case, the readout module can be panel mounted with a minimum of tools. The analyzer accepts power inputs from 97 to 240 VAC 50/60 Hz or 24 VDC and comes with an **ON/OFF switch** located on the rear panel. Alarm and recorder wires are easily installed in **removable terminal strips**.

Sensors connect via a DB-9 connector located on the rear panel of the Mark 25 and the sensors mount easily to any flat surface. In addition, Martek offers **adapter plates** specifically designed to cover the space occupied by other brands of dissolved oxygen analyzers.

Sensors come standard with 6 feet (2 meters) of cable. However, longer cable lengths can be special-ordered from the factory up to lengths of 50 feet.



Specifications

2. Specifications

Parameter	Range	Accuracy	Resolution
Dissolved Oxygen	0-20.00 ppb	+0.1 ppb	0.01 ppb
	0-200.0 ppb	+1.0 ppb	0.1 ppb
	0-2.000 ppm	+0.01 ppm	0.001 ppm
	0-20.00 ppm	+0.1 ppm	0.01 ppm
Temperature	0-50° C	+0.1° C	00.01° C

Power: 85-264 VAC, 47-440 Hz, .4 Amps @ 100VAC or 110-370 VDC
Available with 24 VDC power input

Recorder Output: Four isolated, scaleable 0-20 mA DC analog & RS232C serial ASCII digital output

Alarm Output: Four solid-state relays, 1 amp, 125 VAC, 110 VDC

Weight: 2 lbs (0.9 kg) including one sensor with 10 feet (3 meters)

Construction: Readout Module Case: ABS plastic, NEMA 12 (IP65)
Sensor: Type 316 Stainless Steel, Delrin, CPVC, Platinum & lead, Teflon

Cabling: 8-conductor, 24 gauge, PVC jacket, shielded, 0.25 inch (0.63 cm)

Dimensions: ¼ DIN case, 6.51 x 3.78 x 3.78 (165.5 x 96 x 96 mm) LWH

Installation: Panel mount (mounting hardware included). Recommend mounting flow chamber and sensor vertically.

Flow rate: 50-250 ml/min

Specifications

A. Front View



Figure 2A

B. Rear View




Figure 2B

Specifications

C. Right Side View




Figure 2C

D. Left Side View



Figure 2D

Installation

3. Installation

A. Unpacking And Inspection

Inspect the shipping box for damage. If there is any damage, contact the shipper immediately for instructions. Save the box. If there is no damage than unpack the box. Make sure all items listed are present. If any items are missing contact Martek Instruments at (800) 628 8834




Mark 25 Analyzer



2 Terminal ships



2 Mounting Clips



Mounting Plate




CD Manual

Optional (If Purchased)



Mark 25 D.O Sensor



Electrolyte



Membrane Kit



Shortening Jumper



ABB Probe Adapter



ABB D.O. Sensor



Flow Chamber

Installation

B. Panel Cutout for Monitor




Figure 3B

C. Mounting Analyzer




Figure 3C

D. Sensor Dimensions




Figure 3D-1




Figure 3D-2

E. Flow Chamber Dimensions




Figure 3E

Installation

F. Input and Output connections




Figure 3F-1

To set up the Mark 25 for operation, simply plug the sensor connector in, then plug the AC power cord into a properly grounded outlet. If recorder, digital or alarm outputs are to be used, make certain the Mark 25 is unplugged before connecting the cable to the appropriate recorder or computer. Follow the wiring diagram below for hooking up the Mark 25 alarm and analog recorder outputs:





Figure 3F-2

4. Operation

A. Keyboard and display

The Mark 25 front panel consists of a 4 digit red LED display, 3 parameter and channel LED's, an alarm LED, and an 8-key keypad. The display is used to present all parameter measurements, operator prompts and system errors.



The keys are arranged in two rows, four keys in each row.

The **top row of keys** consist of three color-outlined *function keys* and are used to perform instrument operations such as selecting which parameter to view, what range the parameter is to be viewed in, parameter calibration and system set up.

The **bottom row of keys** are multi-colored, multi-legend keys and are used in conjunction with the function keys. The same colored legends correspond to the same colored function key.

The **arrow keys** are used to view channels, select functions during setup and calibration, and increment or decrement a displayed value.

READ key - When the <READ> key is pressed, the Mark 25 will display **rd**. If one of the bottom keys is selected, the parameter high-lighted in red will be displayed and its corresponding LED lit.

Steps to Reading Dissolved Oxygen





Fig. 4A-1

Steps to Reading Temperature



-Continued on top left of next page-


-Continued from previous page-



Fig. 4A-2

RANGE key - Range changes can be made manually for dissolved oxygen readings only. To change the range, press the <RANGE> key, then select either LOW, MED, or HIGH to display the desired range. If the Mark 25 is setup for auto-ranging, the Mark 25 will display **rg A** as long as the <RANGE> key is pressed.

Steps to Reading Low, 0-20 ppB D.O.



-Continued on top right of this page-

-Continued from bottom left-



Fig. 4A-3

Or

Steps to Reading Med, 0-200ppB D.O.




Fig. 4A-4

Or

Steps to Reading Hi, 0-2 ppM D.O.



-Continued on top left of next page-

-Continued from previous page-




Fig. 4A-5

Or

Steps to Reading Hi, 0-20 ppm D.O.




Fig. 4A-6

Or

Steps to Reading Auto Ranged D.O.




Fig. 4A-7

NOTE: Manually changing the range for dissolved oxygen changes the analog recorder output scaling. See Section **F. Recorder Outputs** for more details.

Viewing a different channel is easily done by pressing the <UP> or <DOWN> arrow key. The parameter LED's to the left of the Mark 25 display also indicate which channel is being viewed. Channel ID's are as follows:

Steps to viewing Channels




Fig. 4A-8

Red LED - Channel 1
 Green LED - Channel 2
 Red/Green LED - Channel 3
 Flashing Red LED - Channel 4

B. The CALIB key

All setup and calibration functions are conducted via the <CALIB> key. The <CALIB> allows you to set the following:

- Calibrate temperature and dissolved oxygen
- Assign and set alarm points
- Assign and set recorder outputs
- Set a password
- Set up an analyzer ID, serial output, and auto-ranging functions

Once the sensors have been connected to the Mark 25, the power cord can be plugged into any outlet supplying 97-240 V AC 50/60 Hz power. When the Mark 25 is switched on, it will immediately start monitoring temperature.


Pressing the <CALIB> key will cause the Mark 25 to display a flashing °C.

If you continue pressing the <DOWN ARROW> key the display will flash the following prompts: **dO**, **ALA**, **rEC**, **PAS**, **uSr**, **tLA**. After **tLA**, the Mark 25 returns to monitoring temperature.

Here are two **basic rules** to remember when using the <CALIB> key:

1. Pressing the <UP ARROW> key will select any flashing prompt.
2. Pressing the <RUN> key will return the Mark 25 to the monitoring mode.

Steps to Viewing Menu Options



-Continued on top right of this page-

-Continued from bottom left-




Fig. 4B-1

C. Calibrating Temperature

The Mark 25 can be calibrated automatically or manually for temperature.

NOTE: Automatic, electronic calibration is a less accurate method of calibration. For best results, the Mark 25 should be calibrated to ASTM or NIST- traceable standards or a referee system such as the **Martek Mark 21 Dissolved Oxygen**.

To calibrate temperature, press the <CALIB> key. The display will flash °C. Press the <UP ARROW> key. The flashing will stop. Next, press the <ZERO> key. The Mark 25 will display **Aut** which is short for Automatic.

To automatically zero calibrate temperature, press the <UP ARROW> key. Calibration bars will briefly appear then the Mark 25 will return to the monitoring mode.

Steps to Auto Zero Temperature Calibration



-Continued on top right of this page-

-Continued from bottom left-




Fig. 4C-1

To manually zero calibrate temperature, simply press the <DOWN ARROW> key when **Aut** is displayed. The Mark 25 will momentarily display three lines then a number indicating the input voltage will appear in the display. Once this number has stabilized, press the <CALIB> key and select the appropriate zero value using the up or down arrow keys (the display defaults to 0 deg. C). When complete, press the <CALIB> key to enter the data into the Mark 25's memory.

Steps to Manual Zero Temperature Calibration





Fig. 4C-2

To span temperature, press the <CALIB> key, then the <UP ARROW> key when the temperature prompt is displayed. Next, select the key. The Mark 25 will display **Aut** which is short for Automatic.

To automatically span calibrate temperature, press the <UP ARROW> key. After the calibration bars appear, the Mark 25 will briefly display a span temperature of **50.0** before returning to monitor mode.

Steps to Auto Span Temperature Calibration



-Continued on top left of next page-

-Continued from previous page-




Fig. 4C-3

The Mark 25 has now been calibrated for temperature.

To manually span calibrate temperature, simply press the <DOWN ARROW> key when **Aut** is displayed. The Mark 25 will momentarily display three lines, then a number indicating the input voltage will appear in the display. Once this number has stabilized, press the <CALIB> key and select the appropriate span value using the up or down arrow keys (the display defaults to 50 deg. C). When complete, press the <CALIB> key to enter the data into the Mark 25's memory.

Steps to Manual Span Temp Calib.




Fig. 4C-4


D. Calibrating Dissolved Oxygen

Calibrating dissolved oxygen follows the same procedure as the temperature calibration. However, if the Mark 25 is not set up for auto-ranging prior to calibration, the desired range must be selected (for information on auto-ranging, see section **K. Auto-ranging**).

To calibrate dissolved oxygen, press the <CALIB> key. The display will flash °C. Press the <DOWN ARROW> key until **dO** is flashing, press the <UP ARROW> key. The flashing will stop. Next, press the <ZERO> key. The Mark 25 will display **Aut** which is short for Automatic.

To automatically zero calibrate dissolved oxygen press the <UP ARROW> key. Calibration bars will briefly appear then the Mark 25 will return to the monitoring mode..

Steps to Auto Zero D.O. Calibration



-Continued on top right of this page-

-Continued from bottom left-





Fig. 4D-1

To manually zero calibrate dissolved oxygen simply press the <DOWN ARROW> key when **Aut** is displayed. The Mark 25 will momentarily display three lines, then a number indicating the input voltage will appear in the display. Once this number has stabilized, press the <CALIB> key and select the appropriate zero value using the up or down arrow keys. When complete, press the <CALIB> key to enter the data into the Mark 25's memory.

Steps to Manual Zero D.O. Calibration



-Continued on top right of this page-

-Continued from bottom left-



Fig. 4D-2

To span calibrate dissolved oxygen, press the <CALIB> key. The display will flash **°C**. Press the <DOWN ARROW> key until **dO** is flashing, press the <UP ARROW> key. The flashing will stop. Next press the key. The Mark 25 will display **Aut** which is short for Automatic.

To automatically span calibrate dissolved oxygen, press the <UP ARROW> key. After the calibration bars appear, the Mark 25 will briefly display a span value of 8.24 before returning to monitor mode.

Steps to Auto Span Dissolved Oxygen



-Continued on top left of next page-

-Continued from previous page-





Fig. 4D-3

The Mark 25 has now been calibrated for dissolved oxygen.

To manually span calibrate dissolved oxygen the dissolved oxygen probe must be exposed to air (**Refer to DO Sensor manual for how to build and operate your purchased DO Sensor before exposing to air**). Press the <DOWN ARROW> key when **Aut** is displayed. The Mark 25 will momentarily display three lines, then a number indicating the input voltage will appear in the display. Once this number has stabilized, press the <CALIB> key and select the appropriate span value using the up or down arrow keys. When complete, press the <CALIB> key to enter the data into the Mark 25's memory.

Steps to Manual Span Dissolved Oxygen Calibration



-Continued on top left of next page-

-Continued from previous page-





Fig. 4D-4

E. Setting Alarms

The Mark 25 has four alarm set points that can be assigned to any parameter on any channel.

To set alarms, press the <CALIB> key. The display will flash °C, press the <DOWN ARROW> key until **ALA** is flashing. Next, press the <UP ARROW> key. The display will prompt with **AL 1** and all parameter LED's will be lit. The <UP ARROW> key can be used to change the alarm set point to 2, 3, or 4.

Steps to Setting Alarms



-Continued on top left of next page-

-Continued from previous page-





Fig. 4E-1

To assign a particular alarm set point, press the <CALIB> key on the desired Alarm output (AL1, 2, 3 and 4). The Mark 25 will display three bars. The bars indicate no alarm set point. Use the <UP> or <DOWN ARROW> keys to select temperature (t), dissolved oxygen (do).

Steps to Setting Alarms Set Points



-Continued on top right of this page-

-Continued from bottom left-




Fig. 4E-2


Press the <CALIB> key to select the desired parameter. The Mark 25 will then display **Lo**. To select a low set point, press the <CALIB> key. If a high alarm set point is desired, use the <UP> or <DOWN ARROW> key to change the display to **hi** then press the <CALIB> key to select.

The Mark 25 will display **.000** though the decimal point may vary depending on the range.

Use the <UP> or <DOWN ARROW> key to change the value to the desired alarm set point. When the desired set point is reached, press the <CALIB> key to set and activate alarm.

NOTE: For convenience, pressing the <RANGE> key will advance the digit left of the decimal point.

Setting Low or High Alarms



-Continued on top left of next page-

-Continued from previous page-



Fig. 4E-3

Setting Low Alarm For Temperature



Press 



Scroll up or down to desired value

Press 

Fig. 4E-4

Setting Hi Alarm For Temperature



Press 



Scroll up or down to desired value

-Continued on top right of this page-

-Continued from bottom left-

Press 


Fig. 4E-5

Setting up Low Alarm for Dissolved Oxygen



Press 

0-20 ppB


$^{\circ}$ C
PPM
PPB 



Or

Press 

0-200 ppB


$^{\circ}$ C
PPM
PPB 



Or

Press 

0-2 ppM

$^{\circ}$ C
PPM
PPB 



Or

-Continued on top left of next page-

-Continued from previous page-




Fig. 4E-6

Setting up Hi Alarm for Dissolved Oxygen





Fig. 4E-7

-Continued from bottom left-



-Continued on top right of this page-

To disable a alarm, return the parameter set point back to three dashes - - - .

Steps to Disabling Alarm Outputs




Fig. 4E-8

Once an alarm set point has been assigned to a particular parameter on a channel, it cannot be assigned to another parameter or channel until it has been disabled.

When the Mark 25 reaches an alarm state, the Alarm LED will light and the alarm relay activate. The factory-set position for the alarm relays is NORMALLY OPEN. To change to a NORMALLY CLOSED position, contact Martek Instruments.

NOTE: The Alarm LED will blink if there are active alarms that are not being viewed and will remain steady if the channel viewed is in an alarm state.

F. Setting Recorder Outputs

The Mark 25 comes standard with four 4-20 mA analog recorder outputs and one RS232 digital output. Like the alarm set points, the four analog recorder outputs can be assigned to any range of any parameter on any channel.


To set recorders , press the <CALIB> key. The display will flash °C, Press the <DOWN ARROW> key until **REC** is flashing. Next, press the <UP ARROW> key. The display will prompt with **ou 1** and all parameter LED's will be lit. The <UP ARROW> key can be used to change the recorder output from alarm set point to 2, 3, or 4.

Steps to Setting Recorder Outputs



-Continued on top left of next page-

-Continued from previous page-



-Continued on top right of this page-

-Continued from bottom left-



Fig. 4F-1

To assign a particular analog output, press the <CALIB> key. The Mark 25 will display three bars. The bars indicate no analog output assigned. Use the <UP> or <DOWN ARROW> keys to select temperature (t), or dissolved oxygen (do).

Steps to Setting Recorder Set Points




Fig. 4F-2

Press the <Range> key to select desired range for dissolved oxygen (**do**).

NOTE: A decimal point will be present for **do** which indicates what range these parameters are currently using. The auto-ranging function must be ON, in order to manually select ranges. (for information on auto-ranging, see section **K. Auto-ranging**).

Steps to Setting Recorder Ranges




Fig. 4F-3

At this point, the standard 4-20 mA output range can be changed to any value desired. In addition, a “balance” is provided to “fine-tune” each end of the recorder range.

To change the lower end of the recorder range, press the <ZERO> key. The Mark 25 will display **4.00**. Use the <UP> or <DOWN ARROW> key to change the number to the desired value. When the desired value is reached, press the <CALIB> key to set the value in memory.

At this point, the Mark 25 will then display **000**. This is the “balance”. Use the <UP> or <DOWN ARROW> key to change the value in order to make the lower end of the recorder range to agree with the external recorder. When the desired balance is reached, press the <CALIB> key to set the value in memory.

At this point, the Mark 25 will then display **0.00**. This is the “actual zero value select”. Use the <UP> or <DOWN ARROW> key to change the value desired to be assigned to the 4ma output. When the desired value is reached, press the <CALIB> key to set the value in memory.

Steps to Setting Low Recorder Out



(Parameter set point depends on how unit was setup)

Press **ZERO**



Scroll up or down to desired mA value

Press **CALIB**



Scroll up or down to align output

Press **CALIB**



or



(Parameter set point depends on how unit was setup)



Scroll up or down to desired low value

Press **CALIB**

Steps to Setting Hi Recorder Out



(Parameter set point depends on how unit was setup)

Press **SPAN**



Scroll up or down to desired mA value

Press **CALIB**



Scroll up or down to align output

Press **CALIB**



or



(Parameter set point depends on how unit was setup)



Scroll up or down to desired Hi value

Press **CALIB**

Fig. 4F-4

-Continued on top left of next page-

-Continued from previous page-


To exit menu press <RUN> key twice.



Fig. 4F-5

To disable any assigned analog recorder output, select the particular output and press the <CALIB> key. Once the parameter is displayed, use the <UP> or <DOWN ARROW> keys until three bars are displayed. Press the <CALIB> key to disable the output.

Steps to Disabling Recorder Outputs



(Parameter set point depends on how unit was setup)



(Press arrow keys until you see three dashes like below)



-Continued on top left of next page-

-Continued from previous page-



Fig. 4F-6

Once a recorder output has been assigned to a particular parameter on a channel, it cannot be assigned to another parameter or channel until it has been disabled.


NOTE: When the auto-ranging function is OFF, changing a conductivity range with an assigned analog output automatically changes the scaling of the recorder output to the new range. When the auto-ranging function is ON, the assigned analog output will remain in the range it was assigned to.

G. Setting the Temperature device

The Mark 25 can be configured to utilize RTD or TLA temperature sensors for water measurements. The setting applies to all channels.

To set the Mark 25 temperature device use with RTD press the <CALIB> key. The display will flash °C. Press the <DOWN ARROW> key until tLA is flashing. Next, press the <UP ARROW> key. The tLA will stop flashing. The <UP ARROW> key can be used to toggle between tLA and RTD. Once the desired device is chosen press the <CALIB> key and the Mark 25 will go to the monitoring display.

Steps to Setting Temperature device



-Continued on top right of this page-

-Continued from bottom left-





Fig. 4G-1

H. Setting the Password

The Mark 25 can be assigned a numeric password to prevent unauthorized personnel from changing any of the settings.

Press the <CALIB> key. The display will flash °C. Press the <DOWN ARROW> key until password prompt, **PAS** appears. Next, press the <UP ARROW> key. The display will prompt with **1999** and all parameter LED's will be lit and flashing. Use the <UP> or <DOWN ARROW> keys to change the displayed value to any number other than 0. When the desired value has been reached, press the <CALIB> key to set and activate the password.

Steps to Setting Password



-Continued on top right of this page-

-Continued from bottom left-



Fig. 4H-1

Once the password is enabled, the display will default to **1999** whenever the password prompt is selected. To gain access to any other function, you must use the arrow keys to scroll to the correct value password then press the <CALIB> key.

To disable the password, use the <UP ARROW> key to move the value to 0 then press the <CALIB> key.

Steps to Disabling Password




Fig. 4H-2

I. Setting the ID Number

The Mark 25 can be assigned a three digit numeric ID number that will be displayed on the digital output.


Press the <CALIB> key. The display will flash °C. Press the <DOWN ARROW> key until user prompt, **uSr** is flashing. Next, press the <UP ARROW> key. The display will prompt with **id** and all parameter LED's will be lit and flashing. When the <CALIB> is pressed, the Mark 25 will display **000**. To assign an ID number, use the <UP> or <DOWN ARROW> keys to change the displayed value to any number other than 000. When the desired value has been reached, press the <CALIB> key to set the ID number.

Steps to Setting ID Number



-Continued on top right of this page-

-Continued from bottom left-



-Continued on top left of next page-

-Continued from previous page-





Fig. 4I-1

To disable the ID number, use the <UP ARROW> key to move the value to 000 then press the <CALIB> key. The ID function will then be disabled.

Steps to Disabling ID



-Continued on top left of next page-

-Continued from previous page-




Fig. 4I-2

J. Changing the Serial Output

The Mark 25 provides a standard RS232 digital output. This output can be configured in one of two ways:

1. Polling - The Mark 25 will provide the digital output only when polled by the host computer.
2. Periodic - The Mark 25 will automatically provide a digital output at a 30 second interval.

When the RS232 digital output is used, calibration is not necessary. However, the receiving computer must be set up to accommodate the Mark 25's digital output configuration:

Baud Rate - **9600**
 Parity - **Even**
 Word length - **7**
 Stop Bit - **1**

A communication program such as PROCOMM or Microsoft HYPERLINK can be used to write data from the Mark 25 to a computer file which can then be


imported into a spreadsheet program such as EXCEL or LOTUS NOTES. The data will be displayed in the following format:

ID,	Chan,	Temp.	DO
ID 000	CH 1	26.7 C DEG.	DO 04.24 ppb
ID 000	CH 2	26.7 C DEG.	DO 03.85 ppb
ID 000	CH 3	26.7 C DEG.	DO 01.88 ppb
ID 000	CH 4	26.7 C DEG.	DO 00.85 ppb

Press the <CALIB> key. The display will flash °C. Press the <DOWN ARROW> key until user prompt appears, **uSr**. Next, press the <UP ARROW> key. The display will prompt with **id** and all parameter LED's will be lit and flashing. Use the <UP> or <DOWN ARROW> key to advance to the serial prompt, **SEr**. When the <CALIB> is pressed, the Mark 25 will display **Pol**. To change the output to periodic interval, press either the <UP> or <DOWN ARROW> key until the Mark 25 displays **PEr**.


To return to the monitor mode, press the <RUN> key.


Steps to Setting Up Serial Output





-Continued on top left of next page-


-Continued from previous page-


Press 





Press 





Press 




Press 




Press 





Press 


-Continued on top right of this page-


-Continued from bottom left-





Press 





Then 





 


Scroll up or down to desired output



Then 



Then 



-Continued on top left of next page-

-Continued from previous page-




Fig. 4J-1

K. Setting the Auto-Ranging Function

The Mark 25 can be set up to automatically range between the low, medium, and high ranges for dissolved oxygen.

Press the <Range> key. If the display shows **rG A** then no changes need to be made the unit is already set for auto ranging. If the display shows **rG 1,2,3 or 4** then next press <UP ARROW> key. The display will show **rG A** for 5 seconds then exit to regular display.

Steps to Setting Up Auto Ranging



-Continued on top right of this page-

-Continued from bottom left-




Fig. 4K-1

5. Maintenance

A. Troubleshooting

The Martek Mark 25 represents over thirty years of experience in conductivity measurements and, as such, has been designed to provide simple, reliable operation for many years.

To obtain optimum performance from the Mark 25, care should be taken to ensure the sensor has adequate flow and is free of obstructions. In addition, it is important to maintain correct calibration on a regular basis.

Comparison of the Mark 25 to a referee system is the preferred method of validation, however, calibration using the Mark 25's internal circuitry is also acceptable.

In the event a problem develops with the Mark 25 that cannot be resolved through recalibration of the unit, Martek recommends resetting the unit. To ensure that resetting the unit is in order contact Martek Instruments directly via telephone, fax, or e-mail located at our website, www.martekinstruments.com.

NOTE: *Resetting the Mark 25 erases all calibration data previously done to unit and replaces it with factory default calibration and settings.*

Steps to Resetting Mark 25

Turn power off with switch in back.

Press and Hold

A rectangular button with a yellow border and the word "CALIB" in black capital letters.

Turn power on with switch in back.



Display shows Bars for 3 sec. only

Press

A rectangular button with a black border and the word "RUN" in yellow capital letters.

While Bars appear

6. Parts List

Part Number	Description
185-10DO	Mark 25 Quad Dissolved Oxygen Analyzer
185-27	Mark 25 Dissolved Oxygen Sensor Only
185-27ABB	Mark 25 ABB Dissolved Oxygen Sensor Only
180-51	Flow Chamber
500133	Electrolyte
400019	Membrane Kit
603173	Shortening Pin
603158	Sensor Extension Cable
140044	8 Terminal Plug Socket
820933	Adapter Plate 7 x 7
820934	Adapter Plate 9.6 x 6
800632	Mounting Brackets

Appendix A

Whipple & Whipple 1911

Temp		Barometric Pressure, mm Mercury										
°C	°F	740	742	744	746	748	750	752	754	756	758	760
2	35.6	13.44	13.47	13.51	13.55	13.58	13.62	13.66	13.69	13.73	13.77	13.80
4	39.2	12.74	12.77	12.81	12.84	12.87	12.91	12.94	12.98	13.01	13.05	13.08
6	42.8	12.09	12.13	12.16	12.19	12.23	12.26	12.29	12.33	12.36	12.39	12.42
8	46.4	11.51	11.54	11.57	11.60	11.63	11.66	11.70	11.73	11.76	11.79	11.82
10	50.0	10.97	11.00	11.03	11.06	11.09	11.12	11.15	11.18	11.21	11.24	11.27
12	53.6	10.47	10.50	10.53	10.56	10.59	10.61	10.64	10.67	10.70	10.73	10.76
14	57.2	10.01	10.04	10.07	10.10	10.12	10.15	10.18	10.21	10.23	10.26	10.29
16	60.8	9.59	9.62	9.64	9.67	9.69	9.72	9.75	9.77	9.80	9.83	9.85
18	64.4	9.20	9.22	9.25	9.27	9.30	9.32	9.35	9.37	9.40	9.43	9.45
20	68.0	8.83	8.86	8.88	8.91	8.93	8.95	8.98	9.00	9.03	9.05	9.08
22	71.6	8.49	8.52	8.54	8.56	8.59	8.61	8.63	8.66	8.68	8.71	8.73
24	75.2	8.18	8.20	8.22	8.24	8.27	8.29	8.31	8.34	8.36	8.38	8.40
26	78.8	7.88	7.90	7.92	7.95	7.97	7.99	8.01	8.03	8.06	8.08	8.10
28	82.4	7.60	7.62	7.64	7.67	7.69	7.71	7.73	7.75	7.77	7.79	7.82
30	86.0	7.34	7.36	7.38	7.40	7.42	7.44	7.46	7.49	7.51	7.53	7.55
32	89.6	7.09	7.11	7.13	7.15	7.17	7.19	7.21	7.23	7.25	7.27	7.29
34	93.2	6.86	6.88	6.90	6.92	6.94	6.96	6.98	7.00	7.02	7.04	7.06
36	96.8	6.64	6.66	6.68	6.69	6.71	6.73	6.75	6.77	6.79	6.81	6.83
38	100.4	6.43	6.44	6.46	6.48	6.50	6.52	6.54	6.56	6.57	6.59	6.61
40	104.0	6.22	6.24	6.26	6.28	6.30	6.31	6.33	6.35	6.37	6.39	6.41

Temp		Barometric Pressure, mm Mercury										
°C	°F	760	762	764	766	768	770	772	774	776	778	780
2	35.6	13.80	13.84	13.88	13.91	13.95	13.99	14.02	14.06	14.10	14.13	14.17
4	39.2	13.08	13.12	13.15	13.19	13.22	13.26	13.29	13.33	13.36	13.40	13.43
6	42.8	12.42	12.46	12.49	12.52	12.56	12.59	12.62	12.66	12.69	12.72	12.75
8	46.4	11.82	11.85	11.88	11.92	11.95	11.98	12.01	12.04	12.07	12.10	12.14
10	50.0	11.27	11.30	11.33	11.36	11.39	11.42	11.45	11.48	11.51	11.54	11.57
12	53.6	10.76	10.79	10.82	10.84	10.87	10.90	10.93	10.96	10.99	11.02	11.04
14	57.2	10.29	10.32	10.34	10.37	10.40	10.43	10.45	10.48	10.51	10.54	10.56
16	60.8	9.85	9.88	9.91	9.93	9.96	9.99	10.01	10.04	10.06	10.09	10.12
18	64.4	9.45	9.48	9.50	9.53	9.55	9.58	9.60	9.63	9.65	9.68	9.70
20	68.0	9.08	9.10	9.13	9.15	9.17	9.20	9.22	9.25	9.27	9.30	9.32
22	71.6	8.73	8.75	8.78	8.80	8.82	8.85	8.87	8.89	8.92	8.94	8.96
24	75.2	8.40	8.43	8.45	8.47	8.50	8.52	8.54	8.56	8.59	8.61	8.63
26	78.8	8.10	8.12	8.14	8.17	8.19	8.21	8.23	8.25	8.28	8.30	8.32
28	82.4	7.82	7.84	7.86	7.88	7.90	7.92	7.94	7.97	7.99	8.01	8.03
30	86.0	7.55	7.57	7.59	7.61	7.63	7.65	7.67	7.69	7.71	7.73	7.75
32	89.6	7.29	7.31	7.34	7.36	7.38	7.40	7.42	7.44	7.46	7.48	7.50
34	93.2	7.06	7.08	7.09	7.11	7.13	7.15	7.17	7.19	7.21	7.23	7.25
36	96.8	6.83	6.85	6.87	6.89	6.90	6.92	6.94	6.96	6.98	7.00	7.02
38	100.4	6.61	6.63	6.65	6.67	6.69	6.71	6.72	6.74	6.76	6.78	6.80
40	104.0	6.41	6.42	6.44	6.46	6.48	6.50	6.51	6.53	6.55	6.57	6.59