
Immersion operation

When installing the sensor in immersion assemblies, please ensure that a sufficient wall distance is observed during operation.

- For this reason, select an installation location in which **a minimum wall distance of 150 mm (6")** is observed even with varying levels or altered flow profiles.

 Mounting in a suspended assembly with chain must therefore be avoided.
- The sensor must immerse at least 40 mm (1.5") into the medium.



CYA611 with pendulum frame

Environment

Storage temperature	-20 to 60 °C (0 to 140 °F)
Ingress protection	IP 68

Endress+Hauser 7