



PC-3100 Brief Instruction of Setting Menu





Relay 2




Relay 2 ON

Relay 2 OFF




Set Point 2 (Lo point)



Dead band (Hysteresis range setting)




Relay(Lo) test OFF/ON

 Clean
(Wash time)




Set wash duration per time (unit: second)



Set off interval duration (unit: hour)



Set hysteresis time to hold relay control (unit: second)



Wash relay test OFF/ON

