


Connect D.O. sensor cable
AX-5000-D4-D10FF



Connect pH sensor cable
AX-1000-H1-N10FF

Attach power
supply cable

White numbers in black boxes indicate connections required