



ITEM NO.	DESCRIPTION	PART NUMBER
1	Slow Blow Fuse: 630 mA, 250 VAC (labeled on front of fuse) - (internal - not shown)	65621-001
2	Slow Blow Fuse: 500 mA, 250 VAC (labeled on front of fuse) - (internal - not shown)	65621-002
3	Magnetic Wand	64238-001
4a	Complete PCB Stack Assembly with Display (110/220 VAC)	65778-001
4b	Complete PCB Stack Assembly with Display (24 VDC)	65778-002
5	Display Board - (internal)	65778-005
7	Display Cover and Lens Assembly	65623-001
8	Connector Chamber and Junction Box Cover	64822-001
9	Cable (Electrode) - 15 feet (see Note 1)	64978-001
10	Cable (Electrode) - 30 feet (see Note 1)	64978-002
11	Cable (Electrode) - 50 feet (see Note 1)	64978-003
12	Cable (Electrode) - 100 feet (see Note 1)	64978-004
13	Cable (Coil) - 15 feet (see Note 1)	64977-001
14	Cable (Coil) - 30 feet (see Note 1)	64977-002
15	Cable (Coil) - 50 feet (see Note 1)	64977-003
16	Cable (Coil) - 100 feet (see Note 1)	64977-004
17	Mounting Bracket Kit	65630-001

Note 1: For remote applications, two cables are required, an electrode cable and a coil cable.

IRP-210-02

M-Series™ is a trademark of Badger Meter, Inc.

7-06

Please see our website at
www.badgermeter.com
for specific contacts.

Copyright©Badger Meter, Inc. 2006. All rights reserved.

Due to continuous research, product improvements and enhancements, Badger Meter reserves the right to change product or system specifications without notice, except to the extent an outstanding contractual obligation exists.



BadgerMeter, Inc.

P.O. Box 245036, Milwaukee, WI 53224-9536
Telephone: (414) 355-0400 / (877) 243-1010
Fax: (414) 355-7499 / (866) 613-9305
www.badgermeter.com